

June 22, 1999 10:00 AM

**Two Bunch Palms
Well 2-99
API # 065-90199**

**Two Bunch Palms
Well 1
API # 065-90200**

**Two Bunch Palms
Well 1A
API # 065-90201**

A site visit was made during the drilling process of Two Bunch Palms 2-99. S&S Pump Company was on location. They were at 95 feet in depth.

The well was located at about 100 feet southwest of the intersection of Two Bunch Palms Trail and Miracle Hill Road. A photo was taken from the center of the intersection toward the well.

The original Two Bunch Palms well is located cross the street at the northwest corner of the intersection behind a locked fence. The well is located inside a vault. I took a photo of the vault from behind the fence. It is an old well. I will name the well Two Bunch Palms 1. There is a pipeline from well Two Bunch Palms 1 buried underground it travels south directly across Two Bunch Palms Trail and along the south side of Two Bunch Palms Trail toward the resort to the west (downhill). Don Sanford of S&S Pump Company stated that this well flows to the surface and then siphons down via the pipeline to the resort.

Located about 40 feet east of well Two Bunch Palms 2-99 is another old well located on property owned by Two Bunch Palms Resorts. It is flowing slightly with water reeds surrounding the well making it virtually impossible to exactly locate the wellhead. I tried to find the well but got my shoes wet. I took a photo of the approximate location. I will call this well Two Bunch Palms 1A.

All these wells well are located near (directly north) the Mission Creek fault. The groundwater is flowing south until it stacks up against the fault. Both Two Bunch 1 and 1A flow to the surface. Well 2-99 undoubtedly will flow also. According to Don Sanford of S&S pump, the wells started flowing after an earthquake in 1986±.